

Work Order ID 96501***96501***

Page 1

Monday, February 11, 2013 2:45:21 PM

Item ID: D2665-2 Accept ***N900040100*** Setup Start ***NS1***
Revision ID: Stop ***NS2***
Item Name: Saddle, RH Fwd Aft Out 206
Start Date: 1/29/2013 Start Qty: 1.00 ***1*** Cust Item ID:
Required Date: 1/30/2013 Req'd Qty: 1.00 ***1*** Customer: CU-DAR001
Reference: RMA RA111469 - *RETURN*

Approvals: Process Plan: *MP* Date: *13-2-11* Tooling: _____ Date: _____ Run Start ***NR1***
QC: _____ Date: _____ SPC (Y/N): _____ Date: _____ Stop ***NR2***

Sequence ID/ Work Center ID	Operation Description	Set Up/ Run Hours	Tool ID	Tool #	Plan Code	Accept Qty	Reject Qty	Reject Number	Insp. Stamp
Draw Nbr	Revision Nbr								
D2665	Rev D								
100		0.00							
100									
QC	Memo	0.00							
Quality Control	INSPECT RA 111469 D2665-2 X 1 B#23785								
	SCRAP PART (OLD REV)								
110		0.00							
110									
Small Fab	Memo	0.00							
Small Fab	SCRAP PART								
120	QC21- Final Inspection - Work Order Release	0.00							
120									
QC	Memo	0.00							
Quality Control									

① *13-02-12**13-02-12**13/2/20**MJS 13-02-20*

Picklist Print

Monday, February 11, 2013 2:45:21 PM

Page 1
T

Work Order ID: 96501

Parent Item: D2665-2

Parent Item Name: Saddle, RH Fwd Aft Out 206

Start Date: 1/29/2013

Required Date: 1/30/2013

Start Qty: 1.00

Required Qty: 1.00

Comments: IPP: C 00.11.01 Removed P/O for Powder Coat - in house process EC
IPP Rev:D As per Rev D 07-03-19 JLM

Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Qty per Kit	Total Qty	Qty Issued	Date Issued	Status
D2665-2 Saddle, RH Fwd Aft Out 206		Manufactured	No				Each	6.0000		1			

Location

Loc Qty

Loc Code

ST434

4

88506

4

ST436

2

82324

2

1 x 23785
mc
13-2-11

RA 111469

Received by: [illegible]
Inspected by: [illegible]

Customer: [illegible]
Customer Contact: ALAN SERRAVALLO
Shipped from: SHERBORN COUNTY AB, CA

Instructions for RA 111469 Multiple parts returned

- D2665-2 B23785 qty x1
 - Scrap! Not at current drawing rev. need work order
- D2666-1 B21101 qty x1
 - Scrap! Not at current drawing rev. need work order
- D2666-2 B22223 qty x1
 - Scrap! Not at current drawing rev. need work order
- D2665-1 B24202 qty x1
 - Scrap! Not at current drawing rev. need work order
- D2652 B91227 qty x32
 - Return to stock under new BATCH #. Need new work order #
- AN3-41A M123355 qty x16
 - Return to stock under new BATCH #. Need new work order #

original

Time Estimate = 2 HOURS

Departments Required: QC (scraping) & Stores (restocking)

Pictures Attached = NO

QTY INSPECTED = SEE ABOVE

**THIS INSTRUCTION SHEET MUST
BE ATTACHED TO THE
RESTOCKING WORK ORDER AT
ALL TIMES!!!!**